Client Vehicle ID: Odometer Reading:

Client Program Options: **Custom Device Options:** 

English.cus Part Number Handset: 8315790 Part Number Controlbox:

Serial Number Handset: Serial Number Controlbox:

Software Version Handset: Software Version Controlbox:

Service Comments:

000000000 149469

XTvol90day072408.opt

8315780

8316246 REV: 2.0 8316247 REV: 2.0

Service Type:

Monitoring Check with

Service Date: Last Calibration:

05/18/2010 14:21:24 02/10/2010 11:08:51

08/16/2010 11:00

Technician:

Next Service:

Location: Bozeman, MT

Monitoring Period:

02/10/2010 to 05/18/2010 (98 days)

Total Events: 11166

## Summary

Initial Tests:		Breath Sample Errors:	
Total Initial Tests:	550	Total Breath Sample Errors:	52
	000	rotal broath bumple birote.	J2
Initial Tests Passed:	488	High Flow:	12
Initial Tests Passed > 0:	100	Short Blow:	11
Initial Test Warnings:	0	Weak Flow:	2
Initial Tests Failed:	14	No Suck:	1
Intial Tests Failed - High BAC:	16	Suck Gradient:	5
Initial Test Refusals:	32	Short Suck:	4
Initial Test Lockouts:	40	Reference Pulse:	0
	16	Sample Pulse:	0
Retests:		Breath Trend:	17
Total Retests:	297	Breath Heater:	0
Total Refests:		Washbottle detection:	_
Retests Passed:	286		0
Retests Passed > 0:	72	Smoke Detected:	0
Retest Warnings:	0	Leakage Detection:	0
Retests Failed:	8	Reverse Flow detection:	0
Retests Failed - High BAC:	8 0	Vehicle Activity:	
Retest Refusals:	· -	Total Engine Runs:	527
. totogr (totagaig).	3	· · · · · · · · · · · · · · · · · · ·	
Retest Request Warnings:	38	Total Untested Engine Runs:	1
Retest Lockouts:	3	Total Engine Offs:	528
	·	Total Ignition Switch On:	611
Power:		Engine Runs - Type 1:	527
Total CB Power Losses:	0	Engine Runs - Type 2:	0
CB Short Power Losses:	0	,	
HS Low Power:	0	Vehicle Activity On:	521
HS Disconnects:	0	Vehicle Activity Off:	9
	8	Total Engine Run Time:	112:38:55
HS Disconnect Violations:	2	rotal Eligino Plan Timo.	112.50.55
Service:		Current Violation Counts:	
Calibrations:	1	Untested Engine Runs:	1
Accuracy Checks:	1	CB Power Losses:	0
•	,	Handset Disconnects:	2
Breath Test Checks:	0	Failed Initial Tests:	- <del>-</del>
Service Reminders:	38	Failed Retests:	14
			8
Codes and PINs:		Initial Test Refusals:	0
Access Code Attempts:	0	Retest Refusals:	3
Accesses:	0	Initial Test High BACs:	16
Free Start PIN Attempts:	-	Retest High BACs:	0
	0	Initial Test Lockouts:	16
,	_		
•	0	Retest Lockouts:	0
Free Starts:  Menu Cal. PIN Attempts:	0	Retest Lockouts: Consecutive Retest Refusals:	0